

**\*\* SPEAR One Week Downtime 2/23-29/04 \*\***

:( Artemis

			Dur.	Mon	Tues	Wed	Thur	Fri	Sat
RSWCF:									
BL1 Wall block removal SLM line exit port dump				x	x	x	x		
Outages:									
SPEAR LCW Down					x	x			
SPEAR:									
Lock up and Search									
<b>BL:</b>									
1. M0 mirror tank for BL 10-1	Marks			x	x	x	x	x	
<b>Facilities:</b>									
Wax floor - experimental area									
<b>Controls:</b>									
<b>Electrical:</b>									
1. <del>BTS B9V examine/repair defective contactor (problem not found)</del>	Rafael			*					
2. <del>Quad power supply 07G-QF1 tripped ; overtemp fault. Check the Klixon connections</del>	Rafael					*			
3. Rebuild the isolation board in Bias white circuit and move it to back Power supply in Bias and Pulse.	Rafael				*	*	* Calib, test	X Calib Pulse	
4. <del>Electrically isolate Cable Tray in 132-102 from Racks 5,6, and 7, in an effort to reduce BPM noise.</del>	Wachter, Martin					*	*		

**\*\* SPEAR One Week Downtime 2/23-29/04 \*\***

	Electrical continued...								
5.	<del>Add ferrite cores to AC power lines, 132-102, Rack 7.</del>	Wachter, Martin				X			
6.	<del>Complete installation of Bunch Length cable, 7/8 inch Heliax, to Girder9-BPM5.</del>	Wachter, Martin					X		
7.	<del>Change burden resistors in DCCT Test Box from 100 ohms to 10 ohms and add inductors.</del>	Taylor, Martin				X			
8.	Characterize noise and performance of Tune Monitor chassis.	Wachter, Martin						X	
9.	<del>Complete crate assy. and installation of Turn By Turn BPM crates.</del>	Wachter, Martin		*	*	X			
10	<del>Clean air filters in 116-101, 132-102.</del>	Theobald					X		
11	<del>Remove un-used cables and chassis; relocate existing chassis to make room for future re-design EPU motor driver chassis in control rack B131-609 [12 hrs]</del>	Dao & Wallters	12 hr	*	X				
12	Identify separate power source for the IQ Analyzers for the motor control centers	Dao	4 hr			x			
13	<del>Investigate the BL9 ID motor driver (fan replaced)</del>	Dao	8 hr				*		
14	SPEAR Kicker pulser IGBT boards: Inspect Repair Replace	PCD		*	*	*	*	X	

**\*\* SPEAR One Week Downtime 2/23-29/04 \*\***

15	Connect independent PS to BL5 end trims (borrow unused channel from BL4 ID)							x	
16	MCORR - measure bandwidth of system	Fernando					Prep	Test	
	<b>MECHANICAL:</b>								
1.	Mechanical inspections	Eddie Guerra)	.5 hr	X					
	<b>Insertion Devices:...</b>								
<del>2.</del>	<del>BL 4/7 ID - setup for closure to min. gap</del>	<del>Poling, Ernst</del>	<del>6 hr</del>		*				
3.	Install BL-5 ID chain guard	Poling, et al	.5 hr		x	x	X instal l		
4.	BL5 ID - EPU magnet repair				x	x	x	x	x
	<b>LCW:...</b>								
<del>5.</del>	<del>Adjust flowswitch set point and valve set point on all the v.c. circuits. (all QFC, BM1, BM2</del>						*		
<del>6.</del>	<del>SPEAR LCW - Install and test strainer basket in the LCW supply</del>		<del>8 hr</del>		*	*			
7.	Verify flowrates on all the Absorber and mask circuits. (found all valves ¼ turn open)		8 hr				x	X	
8.	HCW-- Install new chemical automatic feed pump by	Shin, SEM	4 hr		x				
	<b>Shielding:...</b>								

**\*\* SPEAR One Week Downtime 2/23-29/04 \*\***

	BL1 Shield block - remove/replace Rolling doors - open/close	BL Ops.		✕ ✕				X X	
9	Plug misc. cracks between shielding blocks in the ring	MSG, Scott							
10	<i>SPEAR - install S4 phase II shielding</i>	MSG, Boyce						x	
<del>12</del>	Modify and install cable tray step-up plates (12 out of 19 completed)	<del>Fab shop, Anzur, Ibarra</del>			*	*	✕ 12		
<del>14</del>	<del>White Circuit - install 5hz pad under pulse choke</del>	<del>MSG, ED&amp;M, Delloreo</del>	<del>12 hr</del>			*			
	<b>RF:</b>								
<del>1.</del>	<del>Drain excess oil in RFHVPS, tighten seal in cover plate as necessary Diode Stack Crowbar Remove stacks Replace failed SCRs Re-install stacks</del>	<del>PCD, Park</del>	<del>12 hr</del>		<del>—</del> X	X			
				*		*	<del>—</del> X		*
<del>2.</del>	<del>Reset pressure sensor in RFHVPS LCW to 160 psi</del>	<del>MSG, Nzeadibe</del>				*			
	<b>Vacuum:</b>								
<del>1.</del>	<del>SP3: Ring walkthrough, visual inspection of BL's and Accelerator vacuum systems.</del>	<del>Pak, Wiertel</del>	<del>.5 hr</del>	*					
2.	Troubleshoot IG readback problems w/ED&M 1 of 8 fixed by changing IG controller.	Pak, ED&M, et al		x	x	x			
<del>3.</del>	<del>SP3: Exchange IP PS modified boards (if received)</del>	<del>Pak</del>	<del>4 hr</del>						

